

TESTPASSPORT

練習題



質 量 更 高

服 務 更 好

<https://www.testpassport.net>

免費一年更新服務

Exam : 920-255

**Title : Nortel Secure Router
Ris.2.0 Configuration &
Management**

Version : DEMO

1. Which two commands can be used to edit an access list? (Choose two.)

- A. edit
- B. insert
- C. delete
- D. include

Answer: BC

2. Which is the definition of a Security Zone within the framework of the Nortel Secure Router firewall?

- A. A separate firewall running on each interface individually.
- B. A logical difference between WAN interfaces for security.
- C. A virtual firewall with its own inbound and outbound database.
- D. A representation of each firewall in your WAN and branch network.

Answer:A

3. Which are attributes of a Nortel Secure Router access list filter? (Choose two.)

- A. They are applied to an interface with a direction.
- B. Filters can only be used on WAN side interfaces.
- C. There is an implicit Deny at the end of every filter.
- D. There is an implicit Allow at the end of every filter.

Answer:AC

4. Which mechanism most directly manages SIP traffic on the Nortel Secure Router?

- A. Stateful Inspection
- B. SIP Audio scanning
- C. Source Based Filtering
- D. Application Level Gateway

Answer: D

5. Which command will show the status, number of links, total bandwidth and TX/RX statistic for a bundle named WAN?

- A. show bundle WAN
- B. debug interface bundle
- C. show interface bundle WAN
- D. show module configuration WAN

Answer: C

6. Which connector does a CT3 use?

- A. BNC
- B. RJ45
- C. RJ48C
- D. RS-232

Answer:A

7. Which is the limiting factor to how many T1s can be placed in a single bundle?

- A. Code version
- B. 3 on a 1000, 8 on a 3120
- C. Number available on the platform
- D. Bandwidth divided by modules installed

Answer: C

8. To what lowest level will the Nortel Secure Router products support fractional T1s?

- A. DS0
- B. DS1
- C. DS2
- D. No fractional T1

Answer:A

9. When you type show interface bundle wan1 you see packet dropped above max under the RED statistics. Which are two solutions to this issue? (Choose two.)

- A. Add more bandwidth

- B. Upgrade the hardware
- C. Re-build your WAN bundle
- D. Tune your RED parameters

Answer:AD

10. A Nortel Secure Router is configured to receive clocking from the provider. To what should the clocksource be set?

- A. Line
- B. UTC
- C. SNTP
- D. Internal

Answer:A