

TESTPASSPORT

練習題



質 量 更 高

服 務 更 好

<https://www.testpassport.net>

免費一年更新服務

Exam : HP0-240

**Title : Supporting the Virtual
Array(VA) Storage Family**

Version : DEMO

1.A customer has an entry-level VA cluster solution using MS Windows. A Fibre Channel fabric infrastructure will be installed at a later date. The solution must support two servers in a Windows cluster and provide path failover functionality. Which VA will best suit this customer environment with the least additional investment?

- A.VA7100
- B.VA7110
- C.VA7400
- D.VA7410

Correct:D

2.Which types of interface can be used with AutoPath VA for configuration and maintenance purposes? Select TWO.

- A.GUI
- B.Virtual Front Panel
- C.CVUI
- D.CLI
- E.LVC

Correct:A D

3.Business Copy licenses are based on the _____.

- A.number of hosts in the SAN
- B.amount of raw capacity on the VA
- C.number of hosts in the SAN and the amount of raw capacity on the VA
- D.number of switch ports in the SAN

Correct:B

4.A customer has a VA7110 with a 1024 MB cache and requests an upgrade to the maximum capacity. What must be ordered?

- A.1 x A6187B 1024 MB cache for VA processor
- B.2 x A6187B 1024 MB cache for VA processor
- C.2 x A6186A 512 MB cache for VA processor
- D.4 x A6186A 512 MB cache for VA processor

Correct:B

5.Which components are integrated into the Command View SDM management framework? Select TWO.

- A.Secure Manager
- B.AutoPath
- C.Business Copy
- D.Virtual Front Panel
- E.Zoning

Correct:A C

6.What is the total raw capacity that can be fitted into a 42U rack that has two fully populated VA7410s?

- A.10 TB
- B.20 TB
- C.30 TB
- D.40 TB

Correct:C

7.A customer wants to upgrade a VA7100 to be 2 Gb/s capable. Which accessories must be ordered? Select TWO.

- A.2 x A6218A 7410 VA processor
- B.single mode Fibre Channel cables
- C.2 x A6183AE VA enclosure
- D.2 x A6187A 1024 MB cache (single DIMM)
- E.longwave GBIC modules

Correct:A D

8.With HP18 installed and AutoRAID enabled, which RAID level is primarily used for frequently-written data?

- A.RAID 1+0
- B.RAID 5 DP
- C.RAID 1+0 and RAID 5 DP
- D.RAID 1+0 and VRAID

Correct:A

9.Which disk capacity is NOT supported on the VA7100 and VA7400?

- A.18 GB
- B.36 GB
- C.73 GB
- D.146 GB

Correct:D

10.AutoInclude and AutoFormat are enabled. Rebuild is disabled. What happens when you move a disk from Redundancy Group 1 to Redundancy Group 2?

- A.Nothing.
- B.The disk remains in Redundancy Group 1 and data can still be accessed.
- C.You must first enable this by using the VFP command -g1 -g2 -on.
- D.You must first enable this by using the VFP command cfg -g1 -g2 -on.

Correct:B